





*Worldwide repairs carried out with PolymerMetal®*

**REP-# 067**



Cavitation damages on a flange were repaired by using Ceranium pasty and Hardener CE.

**MultiMetal**  
the MetalExistenceCompany®