




## Worldwide repairs carried out with PolymerMetal®

REP-# 101



A conveying belt of a compost filling plant showed a 120 mm x 130 mm long triangle fracture at the corner. After cleaning and degreasing with MM-Degreaser Z an application of MM-Elastomer 95 with Hardener EL95 was done. Afterwards the conveying belt was put into action again with a tensile stress of 5 bar.

**MultiMetall**  
the MetalExistenceCompany®