




Worldwide repairs carried out with PolymerMetal®

REP-# 116



Repair of oil pipes using MM-metal oL-steelceramic. The origin of the damage was leaky welding seams.

MultiMetall
the MetalExistenceCompany®