




Worldwide repairs carried out with PolymerMetal[®]

REP-# 023



Repairing of a car engine Mercedes Benz near the crankshaft by using MM-metal SS-steelceramic and Hardener yellow. For reinforcement a 1 mm steel plate with the outline of the hole was patched into the engine.

MultiMetall
the MetalExistenceCompany[®]