



*Worldwide repairs carried out with PolymerMetal<sup>®</sup>*

REP-# 033



The seat of a ball bearing of a shaft, which serves for lining up, showed an abrasion of 0,2 mm. First the seat of the ball was turned off by 0,5 mm, then the repair site was cleaned with MM-Degreaser Z. Afterwards MM-metal SS-steel with Hardener yellow was applied. Finally the original shaft diameter was reached again by machining. Now the shaft was operational again without any problems.

**MultiMetall**  
the MetalExistenceCompany<sup>®</sup>