




*Worldwide repairs carried out with PolymerMetal®*

REP-# 031



A cylinder head of a car engine having corroded under water channels was repaired by applying MM-metal SS-steelceramic and Yellow hardener.

**MultiMetall**  
the MetalExistenceCompany®