




Worldwide repairs carried out with PolymerMetal®

REP-# 057



Repair of a corroded gas pipe due to throat gas from blast furnace carried out with Ceramium and Hardener CE.

MultiMetal
the MetalExistenceCompany®