



Worldwide repairs carried out with PolymerMetal®

REP-# 059



Sealing of a cooling water pipe in the high-hazard area of a high-pressure water installation without interrupting operation. The leakage was a 5 cm long crack at a water pressure of 2,5 bar. The sealing was carried out with MM-metal UW and Hardener UW3 without pressure reduction. Materials used were a pre-shaped metal sheeting and MM-Fabric tape (glass fibre).

MultiMetall
the MetalExistenceCompany®