




Worldwide repairs carried out with PolymerMetal®

REP-# 117



A damaged shaft of a conveyer worm was rebuilt using Ceramium. An inspection after 6 months did not reveal any damages on the conveyer worm.

MultiMetall
the MetalExistenceCompany®