



Worldwide repairs carried out with PolymerMetal®

REP-#144



A turbine paddle was worn out caused by a water-sand-mixture. The pasty variant of the PolymerMetal Ceramium was used to rebuild the worn-out areas.

MultiMetal
the MetalExistenceCompany®